








































Weld Bodies VeriFast™ LVDT Quick Reference

No.	VeriFast LVDT Weld Body Style	Insulated Body	Series					Stroke (mm)				Cable Exit Position				Weld Pin Style	Weld Body Foot Print / Other Details
			2	3	4	22	50	22	50	Top Left	Top Right	Top Middle	Pre-Defined				
1	SXAR (Base Mount) 	X	✓	✓	✓	✓	X	✓	✓	X	✓	✓	X	X			
2	SXKR (Base Mount) 	✓	✓	✓	✓	✓	X	X	X	✓	X	✓	X				
3	SXTR (Base Mount) 	X	✓	✓	✓	✓	X	X	X	✓	X	✓	X				
4	SXQR (Base Mount) 	✓	✓	✓	✓	✓	X	X	X	✓	X	✓	X				
5	SXHR (Base Mount) 	✓	✓	✓	✓	✓	X	✓	✓	X	✓	X	X				
6	SXJR (Base Mount) 	✓	✓	✓	✓	✓	X	✓	✓	X	✓	X	X				
7	SXVR (Base Mount) 	X	✓	X	X	✓	X	X	X	✓	X	✓	X				
8	SXWR (Base Mount) 	✓	✓	X	X	✓	X	X	X	✓	X	✓	X				

✓=Recommended X=Not Available ✓=Available, Not Recommended

Weld Bodies VeriFast™ LVDT Quick Reference

No.	VeriFast LVDT Weld Body Style	Insulated Body	Series					Stroke (mm)				Cable Exit Position				Weld Pin Style	Weld Body Foot Print / Other Details
			2	3	4	22	50	22	50	Top Left	Top Right	Top Middle	Pre-Defined				
9	SXZR (Base Mount) 	X	✓	✓	✓	✓	X	✓	X	X	✓	X	X				
10	SXCR (Tapered) 	X	X	✓	X	✓	X	X	X	X	X	✓	X				
11	SXGR (Threaded) 	X	X	✓	X	✓	X	X	X	X	X	✓	X				
12	Clamp Mount 	X	✓	✓	✓	✓	✓	✓	X	X	X	✓	X				
13	SYVR (Base Mount) 	X	✓	✓	✓	✓	X	✓	X	X	✓	X	X				

✓=Recommended X=Not Available ✓=Available, Not Recommended